

MV 606-P19734US00  
10/518,346  
MULTIVAC Sepp Haggenmüller GmbH & Co. KG

**Partial Translation of DE 22 59 547**

Page 4, first and second paragraph:

In Fig. 5 it is shown how the package looks like after vacuum has been applied and after the edge of the cavity has been sealed under maintaining the vacuum with the covering film cut 18. One recognizes thereby creases 20 which appear after the sealed package is removed from the vacuum, i.e. after the package is again under atmospheric pressure.

In Fig. 6, one recognizes the package in a condition which is reached after the package of Fig. 5 has been exhibited during a time of around 5 seconds to a temperature of 120°C. The creases have disappeared